

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
PHILIPPINES				
Total	18,162,497	13,626,566	191,692	885,608
Concrete/Brick/Stone	6,687,348	6,340,206	145,779	101,633
Wood	3,592,454	2,595,477	13,740	104,644
Half Concrete/Brick/Stone and Half Wood	3,778,334	3,002,102	25,256	569,998
Galvanized Iron/Aluminum	222,833	169,935	3,783	28,755
Bamboo/Sawali/Cogon/Nipa	3,604,808	1,412,278	-	74,081
Asbestos	6,027	4,591	170	232
Glass	4,273	2,702	483	487
Makeshift/Salvaged/Improvised Materials	105,518	46,738	-	2,328
Others/Not Reported	159,681	51,969	2,460	3,406
No Walls	1,221	568	21	44
NCR				
Total	2,485,637	2,084,715	85,520	208,505
Concrete/Brick/Stone	1,244,843	1,133,949	68,223	30,648
Wood	393,184	321,155	6,057	23,474
Half Concrete/Brick/Stone and Half Wood	765,239	590,908	9,947	147,202
Galvanized Iron/Aluminum	28,259	20,444	706	4,903
Bamboo/Sawali/Cogon/Nipa	3,142	1,612	-	205
Asbestos	1,042	633	73	30
Glass	901	496	165	110
Makeshift/Salvaged/Improvised Materials	24,634	10,136	-	560
Others/Not Reported	24,142	5,312	333	1,366
No Walls	251	70	16	7
CAR				
Total	317,184	287,105	7,619	5,398
Concrete/Brick/Stone	107,814	99,189	6,850	934
Wood	58,352	51,840	85	480
Half Concrete/Brick/Stone and Half Wood	62,461	58,121	582	3,162
Galvanized Iron/Aluminum	57,957	57,208	65	349
Bamboo/Sawali/Cogon/Nipa	25,401	16,736	-	443
Asbestos	31	18	2	-
Glass	122	100	5	-
Makeshift/Salvaged/Improvised Materials	691	510	-	3
Others/Not Reported	4,347	3,378	30	27
No Walls	8	5	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
REGION I				
Total	940,819	807,496	4,759	50,664
Concrete/Brick/Stone	471,714	458,704	3,217	5,341
Wood	62,092	51,600	253	2,645
Half Concrete/Brick/Stone and Half Wood	210,472	169,099	874	33,680
Galvanized Iron/Aluminum	15,088	11,721	269	2,224
Bamboo/Sawali/Cogon/Nipa	170,130	110,326	-	6,370
Asbestos	299	209	3	16
Glass	337	162	27	107
Makeshift/Salvaged/Improvised Materials	4,044	2,321	-	133
Others/Not Reported	6,617	3,338	116	148
No Walls	26	16	-	-
REGION II				
Total	653,594	544,412	4,059	28,581
Concrete/Brick/Stone	294,927	287,259	3,184	2,193
Wood	95,664	75,334	112	2,941
Half Concrete/Brick/Stone and Half Wood	122,140	101,370	550	17,089
Galvanized Iron/Aluminum	11,143	8,784	96	1,566
Bamboo/Sawali/Cogon/Nipa	123,288	67,874	-	4,623
Asbestos	557	519	4	14
Glass	90	66	4	17
Makeshift/Salvaged/Improvised Materials	1,786	1,032	-	53
Others/Not Reported	3,993	2,171	109	85
No Walls	6	3	-	-
REGION III				
Total	2,008,012	1,703,211	14,902	136,862
Concrete/Brick/Stone	1,181,252	1,145,613	9,398	14,872
Wood	147,339	116,117	1,109	8,513
Half Concrete/Brick/Stone and Half Wood	452,149	335,593	3,476	100,560
Galvanized Iron/Aluminum	19,368	12,920	431	4,172
Bamboo/Sawali/Cogon/Nipa	169,128	78,507	-	7,819
Asbestos	306	178	13	10
Glass	747	527	63	65
Makeshift/Salvaged/Improvised Materials	11,295	5,908	-	348
Others/Not Reported	26,400	7,833	411	503
No Walls	28	15	1	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
REGION IV-A				
Total	2,472,568	2,135,790	26,547	141,122
Concrete/Brick/Stone	1,328,348	1,279,674	19,252	20,912
Wood	329,633	263,195	1,695	13,663
Half Concrete/Brick/Stone and Half Wood	580,732	466,694	4,409	96,890
Galvanized Iron/Aluminum	28,750	22,333	850	3,783
Bamboo/Sawali/Cogon/Nipa	166,972	86,917	-	4,865
Asbestos	910	732	25	49
Glass	654	502	50	25
Makeshift/Salvaged/Improvised Materials	18,511	9,105	-	552
Others/Not Reported	17,999	6,608	266	382
No Walls	59	30	-	1
REGION IV-B				
Total	542,937	281,725	2,566	27,137
Concrete/Brick/Stone	136,164	128,825	1,679	2,037
Wood	48,891	31,611	157	1,766
Half Concrete/Brick/Stone and Half Wood	91,746	66,172	451	16,267
Galvanized Iron/Aluminum	4,097	1,954	196	1,128
Bamboo/Sawali/Cogon/Nipa	253,177	50,919	-	5,794
Asbestos	166	136	-	6
Glass	88	34	7	10
Makeshift/Salvaged/Improvised Materials	2,699	533	-	46
Others/Not Reported	5,821	1,524	75	79
No Walls	88	17	1	4
REGION V				
Total	1,016,058	541,378	19,095	42,821
Concrete/Brick/Stone	351,552	301,748	17,388	7,603
Wood	185,998	83,366	425	4,031
Half Concrete/Brick/Stone and Half Wood	165,167	100,796	820	23,870
Galvanized Iron/Aluminum	9,230	4,755	292	2,098
Bamboo/Sawali/Cogon/Nipa	283,544	45,300	-	4,940
Asbestos	168	93	21	4
Glass	122	52	15	5
Makeshift/Salvaged/Improvised Materials	12,890	3,440	-	155
Others/Not Reported	7,368	1,824	134	114
No Walls	19	4	-	1

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
REGION VI				
Total	1,382,697	978,680	4,193	59,256
Concrete/Brick/Stone	332,036	316,302	3,098	4,099
Wood	145,294	118,424	153	4,639
Half Concrete/Brick/Stone and Half Wood	269,744	219,494	559	32,487
Galvanized Iron/Aluminum	11,254	7,295	141	2,104
Bamboo/Sawali/Cogon/Nipa	609,560	309,329	-	15,678
Asbestos	393	339	3	23
Glass	207	160	5	7
Makeshift/Salvaged/Improvised Materials	6,845	4,137	-	139
Others/Not Reported	7,310	3,184	234	76
No Walls	54	16	-	4
REGION VII				
Total	1,323,959	1,033,491	5,701	48,709
Concrete/Brick/Stone	304,164	291,934	3,644	3,674
Wood	325,602	271,618	746	8,808
Half Concrete/Brick/Stone and Half Wood	337,502	294,723	925	28,828
Galvanized Iron/Aluminum	9,630	6,534	170	1,630
Bamboo/Sawali/Cogon/Nipa	328,560	160,399	-	5,332
Asbestos	316	240	7	28
Glass	450	267	65	92
Makeshift/Salvaged/Improvised Materials	6,485	3,643	-	67
Others/Not Reported	10,841	3,821	143	227
No Walls	409	312	1	23
REGION VIII				
Total	799,640	446,767	2,521	31,432
Concrete/Brick/Stone	190,735	179,925	1,817	2,226
Wood	209,975	117,758	161	5,161
Half Concrete/Brick/Stone and Half Wood	125,419	87,798	400	19,009
Galvanized Iron/Aluminum	5,201	2,669	72	919
Bamboo/Sawali/Cogon/Nipa	256,919	55,518	-	3,955
Asbestos	148	108	3	10
Glass	84	54	6	6
Makeshift/Salvaged/Improvised Materials	3,326	855	-	57
Others/Not Reported	7,746	2,042	62	86
No Walls	87	40	-	3

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
REGION IX				
Total	633,555	362,205	1,859	14,257
Concrete/Brick/Stone	85,955	82,663	987	738
Wood	259,170	171,862	338	4,309
Half Concrete/Brick/Stone and Half Wood	74,993	63,192	378	6,636
Galvanized Iron/Aluminum	3,125	1,661	51	594
Bamboo/Sawali/Cogon/Nipa	204,726	41,169	-	1,908
Asbestos	304	271	3	8
Glass	57	34	12	5
Makeshift/Salvaged/Improvised Materials	1,477	404	-	9
Others/Not Reported	3,721	938	90	50
No Walls	27	11	-	-
REGION X				
Total	793,177	639,610	2,122	21,974
Concrete/Brick/Stone	177,284	172,201	1,304	1,690
Wood	356,897	288,694	379	7,084
Half Concrete/Brick/Stone and Half Wood	135,744	119,486	333	11,001
Galvanized Iron/Aluminum	3,698	2,078	67	694
Bamboo/Sawali/Cogon/Nipa	113,027	53,816	-	1,427
Asbestos	264	236	2	3
Glass	116	74	9	6
Makeshift/Salvaged/Improvised Materials	2,706	1,469	-	41
Others/Not Reported	3,423	1,547	27	28
No Walls	18	9	1	-
REGION XI				
Total	879,929	678,834	2,317	15,075
Concrete/Brick/Stone	198,116	194,164	1,512	912
Wood	257,230	214,259	338	3,044
Half Concrete/Brick/Stone and Half Wood	138,297	125,774	322	7,697
Galvanized Iron/Aluminum	4,087	2,800	49	424
Bamboo/Sawali/Cogon/Nipa	269,151	135,117	-	2,880
Asbestos	470	404	2	6
Glass	82	64	7	2
Makeshift/Salvaged/Improvised Materials	3,058	1,631	-	46
Others/Not Reported	9,437	4,620	87	64
No Walls	1	1	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Total Occupied Housing Units	Construction Materials of the Roof		
		Galvanized Iron/Aluminum	Tile Concrete/Clay Tile	Half Galvanized Iron and Half Concrete
REGION XII				
Total	794,898	530,455	1,938	21,106
Concrete/Brick/Stone	167,045	163,665	1,045	1,332
Wood	140,278	100,727	340	3,177
Half Concrete/Brick/Stone and Half Wood	122,493	108,010	279	10,155
Galvanized Iron/Aluminum	4,677	3,060	73	730
Bamboo/Sawali/Cogon/Nipa	352,062	151,812	-	5,550
Asbestos	224	165	2	9
Glass	58	32	6	15
Makeshift/Salvaged/Improvised Materials	2,339	864	-	67
Others/Not Reported	5,718	2,117	193	71
No Walls	4	3	-	-
CARAGA				
Total	450,405	227,972	1,082	11,798
Concrete/Brick/Stone	70,141	65,018	614	830
Wood	273,447	114,559	165	3,984
Half Concrete/Brick/Stone and Half Wood	55,210	41,561	223	6,126
Galvanized Iron/Aluminum	1,788	941	62	428
Bamboo/Sawali/Cogon/Nipa	44,999	4,687	-	400
Asbestos	217	175	-	2
Glass	31	23	3	-
Makeshift/Salvaged/Improvised Materials	1,197	371	-	11
Others/Not Reported	3,352	635	15	17
No Walls	23	2	-	-
ARMM				
Total	667,428	342,720	4,892	20,911
Concrete/Brick/Stone	45,258	39,373	2,567	1,592
Wood	303,408	203,358	1,227	6,925
Half Concrete/Brick/Stone and Half Wood	68,826	53,311	728	9,339
Galvanized Iron/Aluminum	5,481	2,778	193	1,009
Bamboo/Sawali/Cogon/Nipa	231,022	42,240	-	1,892
Asbestos	212	135	7	14
Glass	127	55	34	15
Makeshift/Salvaged/Improvised Materials	1,535	379	-	41
Others/Not Reported	11,446	1,077	135	83
No Walls	113	14	1	1

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
PHILIPPINES					
Total	278,163	2,955,226	62,320	49,402	113,520
Concrete/Brick/Stone	17,565	54,839	2,265	13,500	11,561
Wood	144,028	708,263	9,679	10,395	6,228
Half Concrete/Brick/Stone and Half Wood	44,244	120,401	3,761	5,215	7,357
Galvanized Iron/Aluminum	11,557	7,510	426	418	449
Bamboo/Sawali/Cogon/Nipa	57,533	2,032,506	7,221	12,911	8,278
Asbestos	291	-	-	593	150
Glass	231	-	-	105	265
Makeshift/Salvaged/Improvised Materials	1,121	15,707	38,540	552	532
Others/Not Reported	1,544	15,695	336	5,605	78,666
No Walls	49	305	92	108	34
NCR					
Total	59,757	1,399	17,424	8,694	19,623
Concrete/Brick/Stone	5,200	38	232	4,389	2,164
Wood	37,699	192	2,885	850	872
Half Concrete/Brick/Stone and Half Wood	13,861	237	826	783	1,475
Galvanized Iron/Aluminum	1,920	31	68	134	53
Bamboo/Sawali/Cogon/Nipa	337	839	110	10	29
Asbestos	70	-	-	171	65
Glass	34	-	-	34	62
Makeshift/Salvaged/Improvised Materials	395	34	13,150	196	163
Others/Not Reported	237	28	94	2,053	14,719
No Walls	4	-	59	74	21
CAR					
Total	1,440	12,788	204	1,395	1,235
Concrete/Brick/Stone	131	74	41	420	175
Wood	513	5,076	8	301	49
Half Concrete/Brick/Stone and Half Wood	215	196	20	96	69
Galvanized Iron/Aluminum	114	162	1	7	51
Bamboo/Sawali/Cogon/Nipa	438	7,190	20	534	40
Asbestos	-	-	-	11	-
Glass	14	-	-	1	2
Makeshift/Salvaged/Improvised Materials	7	53	111	5	2
Others/Not Reported	8	36	3	19	846
No Walls	-	1	-	1	1

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
REGION I					
Total	14,825	56,061	2,100	1,001	3,913
Concrete/Brick/Stone	2,739	918	87	218	490
Wood	3,412	3,926	121	47	88
Half Concrete/Brick/Stone and Half Wood	4,340	1,793	232	143	311
Galvanized Iron/Aluminum	526	286	18	11	33
Bamboo/Sawali/Cogon/Nipa	3,685	48,514	491	374	370
Asbestos	16	-	-	40	15
Glass	12	-	-	19	10
Makeshift/Salvaged/Improvised Materials	21	393	1,143	15	18
Others/Not Reported	74	227	7	129	2,578
No Walls	-	4	1	5	-
REGION II					
Total	4,160	69,083	606	1,274	1,419
Concrete/Brick/Stone	159	1,780	40	174	138
Wood	1,380	15,538	58	237	64
Half Concrete/Brick/Stone and Half Wood	488	2,444	42	75	82
Galvanized Iron/Aluminum	326	352	2	11	6
Bamboo/Sawali/Cogon/Nipa	1,770	48,170	130	579	142
Asbestos	4	-	-	15	1
Glass	-	-	-	1	2
Makeshift/Salvaged/Improvised Materials	12	357	326	5	1
Others/Not Reported	21	440	7	177	983
No Walls	-	2	1	-	-
REGION III					
Total	24,233	94,201	6,643	3,318	24,642
Concrete/Brick/Stone	2,527	2,612	717	1,290	4,223
Wood	10,901	8,811	717	388	783
Half Concrete/Brick/Stone and Half Wood	5,014	4,957	351	352	1,846
Galvanized Iron/Aluminum	1,288	405	34	21	97
Bamboo/Sawali/Cogon/Nipa	4,189	76,149	678	801	985
Asbestos	24	-	-	72	9
Glass	34	-	-	11	47
Makeshift/Salvaged/Improvised Materials	135	676	4,092	40	96
Others/Not Reported	120	585	52	340	16,556
No Walls	1	6	2	3	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
REGION IV-A					
Total	35,147	105,112	11,106	4,406	13,338
Concrete/Brick/Stone	2,657	1,445	219	2,392	1,797
Wood	20,315	28,122	1,576	456	611
Half Concrete/Brick/Stone and Half Wood	6,501	4,298	592	301	1,047
Galvanized Iron/Aluminum	1,196	338	174	21	55
Bamboo/Sawali/Cogon/Nipa	4,010	69,224	922	685	349
Asbestos	23	-	-	73	8
Glass	47	-	-	16	14
Makeshift/Salvaged/Improvised Materials	191	1,006	7,566	20	71
Others/Not Reported	207	662	52	442	9,380
No Walls	-	17	5	-	6
REGION IV-B					
Total	6,480	218,814	1,254	1,667	3,294
Concrete/Brick/Stone	202	2,804	13	416	188
Wood	1,868	13,143	52	181	113
Half Concrete/Brick/Stone and Half Wood	784	7,619	38	212	203
Galvanized Iron/Aluminum	359	443	2	1	14
Bamboo/Sawali/Cogon/Nipa	3,193	191,916	179	585	591
Asbestos	7	-	-	14	3
Glass	35	-	-	-	2
Makeshift/Salvaged/Improvised Materials	10	1,130	958	11	11
Others/Not Reported	22	1,702	7	243	2,169
No Walls	-	57	5	4	-
REGION V					
Total	6,794	389,763	7,522	4,423	4,262
Concrete/Brick/Stone	304	22,291	471	1,195	552
Wood	2,589	93,544	980	747	316
Half Concrete/Brick/Stone and Half Wood	919	37,310	473	679	300
Galvanized Iron/Aluminum	445	1,539	63	20	18
Bamboo/Sawali/Cogon/Nipa	2,468	228,314	1,159	864	499
Asbestos	17	-	-	29	4
Glass	1	-	-	-	49
Makeshift/Salvaged/Improvised Materials	30	4,763	4,329	145	28
Others/Not Reported	20	1,991	47	742	2,496
No Walls	1	11	-	2	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
REGION VI					
Total	16,483	312,699	2,465	4,247	4,674
Concrete/Brick/Stone	500	6,789	60	896	292
Wood	5,466	15,957	126	248	281
Half Concrete/Brick/Stone and Half Wood	2,363	13,644	224	699	274
Galvanized Iron/Aluminum	792	788	14	98	22
Bamboo/Sawali/Cogon/Nipa	7,258	273,590	696	1,962	1,047
Asbestos	12	-	-	15	1
Glass	4	-	-	6	25
Makeshift/Salvaged/Improvised Materials	44	1,139	1,335	32	19
Others/Not Reported	30	777	10	287	2,712
No Walls	14	15	-	4	1
REGION VII					
Total	17,626	204,382	2,722	3,806	7,522
Concrete/Brick/Stone	1,208	2,737	45	540	382
Wood	8,861	34,180	319	541	529
Half Concrete/Brick/Stone and Half Wood	2,556	9,399	161	371	539
Galvanized Iron/Aluminum	855	362	11	38	30
Bamboo/Sawali/Cogon/Nipa	3,989	155,677	408	1,975	780
Asbestos	15	-	-	22	4
Glass	13	-	-	4	9
Makeshift/Salvaged/Improvised Materials	42	927	1,749	24	33
Others/Not Reported	75	1,072	14	278	5,211
No Walls	12	28	15	13	5
REGION VIII					
Total	12,114	298,625	1,355	1,686	5,140
Concrete/Brick/Stone	346	5,955	46	205	215
Wood	5,227	80,733	181	363	391
Half Concrete/Brick/Stone and Half Wood	1,470	16,177	56	252	257
Galvanized Iron/Aluminum	431	1,082	9	10	9
Bamboo/Sawali/Cogon/Nipa	4,556	191,556	278	577	479
Asbestos	4	-	-	20	3
Glass	12	-	-	1	5
Makeshift/Salvaged/Improvised Materials	17	1,597	776	12	12
Others/Not Reported	49	1,484	9	245	3,769
No Walls	2	41	-	1	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
REGION IX					
Total	8,490	242,312	1,005	979	2,448
Concrete/Brick/Stone	184	1,119	78	104	82
Wood	4,257	77,486	258	431	229
Half Concrete/Brick/Stone and Half Wood	849	3,741	63	51	83
Galvanized Iron/Aluminum	476	312	2	25	4
Bamboo/Sawali/Cogon/Nipa	2,636	158,242	210	282	279
Asbestos	10	-	-	12	-
Glass	2	-	-	2	2
Makeshift/Salvaged/Improvised Materials	31	633	388	7	5
Others/Not Reported	45	767	2	65	1,764
No Walls	-	12	4	-	-
REGION X					
Total	10,081	112,359	2,612	1,945	2,474
Concrete/Brick/Stone	476	1,192	108	119	194
Wood	5,858	52,850	953	553	526
Half Concrete/Brick/Stone and Half Wood	822	3,375	395	119	213
Galvanized Iron/Aluminum	672	176	5	2	4
Bamboo/Sawali/Cogon/Nipa	2,164	53,762	542	1,051	265
Asbestos	1	-	-	-	22
Glass	3	-	-	1	23
Makeshift/Salvaged/Improvised Materials	49	519	600	16	12
Others/Not Reported	36	477	9	84	1,215
No Walls	-	8	-	-	-
REGION XI					
Total	17,030	158,142	1,893	1,976	4,662
Concrete/Brick/Stone	290	830	46	143	219
Wood	11,277	27,180	501	300	331
Half Concrete/Brick/Stone and Half Wood	704	3,492	82	79	147
Galvanized Iron/Aluminum	592	209	5	2	6
Bamboo/Sawali/Cogon/Nipa	4,034	124,914	461	1,290	455
Asbestos	21	-	-	32	5
Glass	4	-	-	1	4
Makeshift/Salvaged/Improvised Materials	15	558	787	11	10
Others/Not Reported	93	959	11	118	3,485
No Walls	-	-	-	-	-

Table 8. Occupied Housing Units by Construction Materials of the Roof and Outer Walls and Region: 2007

Construction Materials of the Outer Walls and Region	Construction Materials of the Roof				
	Wood	Cogon/Nipa/ Anahaw	Makeshift/ Salvaged/ Improvised materials	Asbestos/ Others	Not Reported
REGION XII					
Total	13,892	220,172	1,717	1,744	3,874
Concrete/Brick/Stone	220	374	27	160	222
Wood	6,270	29,108	167	217	272
Half Concrete/Brick/Stone and Half Wood	1,066	2,517	66	190	210
Galvanized Iron/Aluminum	518	260	8	5	23
Bamboo/Sawali/Cogon/Nipa	5,724	186,186	704	1,070	1,016
Asbestos	37	-	-	9	2
Glass	1	-	-	-	4
Makeshift/Salvaged/Improvised Materials	8	647	741	3	9
Others/Not Reported	48	1,079	4	90	2,116
No Walls	-	1	-	-	-
CARAGA					
Total	10,788	194,362	804	1,537	2,062
Concrete/Brick/Stone	131	3,214	20	253	61
Wood	8,029	145,141	442	920	207
Half Concrete/Brick/Stone and Half Wood	547	6,521	29	166	37
Galvanized Iron/Aluminum	133	216	3	2	3
Bamboo/Sawali/Cogon/Nipa	1,897	37,858	47	44	66
Asbestos	9	-	-	29	2
Glass	-	-	-	4	1
Makeshift/Salvaged/Improvised Materials	11	533	261	6	4
Others/Not Reported	29	861	2	112	1,681
No Walls	2	18	-	1	-
ARMM					
Total	18,823	264,952	888	5,304	8,938
Concrete/Brick/Stone	291	667	15	586	167
Wood	10,106	77,276	335	3,615	566
Half Concrete/Brick/Stone and Half Wood	1,745	2,681	111	647	264
Galvanized Iron/Aluminum	914	549	7	10	21
Bamboo/Sawali/Cogon/Nipa	5,185	180,405	186	228	886
Asbestos	21	-	-	29	6
Glass	15	-	-	4	4
Makeshift/Salvaged/Improvised Materials	103	742	228	4	38
Others/Not Reported	430	2,548	6	181	6,986
No Walls	13	84	-	-	-